

FITTED
20/4

Fault Report

Customer Name

STRACHAN

Date:

20/04/2026

Customer Reference:

51427

Filter:

GREG W

Salesperson: GREG.

Salesperson called: Yes/~~No~~

Fault Description: 3x VISION, NO FABRIC FACING
REQUIRE FABRIC FACE.

Action to correct: INSERT FABRIC FACE.

Problem fixed on site: ~~Yes~~ No

Further action required:

This is SALES / PROCESSING Communication Breakdown
Previous vision orders came with fabric faces without being on
form.