

Fault Report

Customer Name: MCKIMMIE	Date: 20/04/26
Customer Reference: 51776	Fitter: AMO
Salesperson: BILL	Salesperson called: Yes/No
Order Inputting Error <input type="checkbox"/>	Mismeasure <input checked="" type="checkbox"/>
Production Error <input type="checkbox"/>	Supplier Error <input type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Problem fixed on site: Yes/No	
Blind Type and number: BOTH BLINDS VISION	
Fault Description: TOO BIG AND MEASURED IN WRONG PLACE	
Action to correct: REORDER RECESS 2080 x 1220 1476 x 1015	

