

S 345377  
Webster.R1

# Fault Report

Customer Name: Webster	Date: 3/5/22
Customer Reference: 345377	Fitter: CRAIG M
Salesperson:	Salesperson called: Yes/No
Blind Type and number:	
Fault Description: Need 1 x 30 x 40 mm batten couldn't fit behind shutter tried to cut batten but cut wrong (couldn't move shutter to fit behind.	
Action to correct: Need 1 x 30 x 40 mm batten	
Problem fixed on site: Yes/No	
Further action required: Batten Ordered @ DBG	