

# Fault Report

Customer Name:	<i>LIGHT FOOT</i>	Date:	<i>16/11/21</i>
Customer Reference:	<i>349806</i>	Fitter:	<i>ADAM</i>
Salesperson:	<i>SHAWN</i>	Salesperson called: Yes/No	<i>YES</i>
Blind Type and number:	<i>EXPRESSION VEN X 1</i>		
Fault Description:	<i>ORDERED 38mm SLOT &amp; 50mm WAS DELIVERED.</i>		
Action to correct:	<i>ORDER NEW BLIND</i>		
Problem fixed on site: Yes/No	<i>NO</i>		
Further action required:			

# Rainbow Blinds

Rainbow Blinds & Interiors  
 51 Canyon Road  
 Exca Slor Park  
 Wishaw  
 ML1 0EG  
 T 0183 351 838  
 F 0183 351 999  
 SA 88 Rainrow-0183351000

C.R. - WRONG SIZE SLAT  
 DELIVERED  
 FACTORY ERROR

Mrs. LIGHTFOOT - 349806

## Order Form

Special instructions

Telephone: \_\_\_\_\_

Email: \_\_\_\_\_

Signature: \_\_\_\_\_

349806 LIGHTFOOT  
 PLEASE REFER TO THIS NUMBER

Date: 16-11-21

Retailer: B.P. LTD

Address: SPENTWOOD

Date Required: \_\_\_\_\_

BLIND SIZE CONTROLS SPACERS PELMET ORDER

Slat Range and Colour	Slat Size	Slat Spacing	Blind Width	Blind Depth	Blind Length	Blind Type	Blind Material	Blind Finish	Blind Control	Blind Price	Blind Qty	Blind Total
SNOW EXPRESSIONS	2700	1/2	1485	2095	35	1/2	2095	1485	1/2	2700	1	2700

Blind Reference	Blind Description	Blind Price	Blind Qty	Blind Total
1	B/BSD	2700	1	2700
2				
3				
4				
5				
6				
7				
8				

NOTE: ALL MEASUREMENTS TO BE TAKEN AS SHOWN

PLEASE REFER TO THIS NUMBER  
 THE PRICE IS SUBJECT TO CHANGE  
 THIS ORDER IS VALID FOR 30 DAYS FROM DATE OF ORDER