

G 348866
Plant / R1

Fault Report

Customer Name: PLANT 348866	Date: 21/4/22
Customer Reference:	Fitter: GRAEME
Salesperson:	Salesperson called: Yes/No <input checked="" type="radio"/>
Blind Type and number: FRONT BEDROOM SHUTTER	
Fault Description: F BED SHUTTER RIGHT PANELS ARE DIFFERENT RAIL SIZES TO F BED LEFT. NEED TO MATCH FBED LEFT (SMALLER RAIL SIZE) SUPPLIER HAS SENT WRONG PANELS.	
Action to correct: SUPPLIER CONTACTED. RE MAKE PANELS.	
Problem fixed on site: Yes/No	
Further action required: Goodwood Sent In Wrong Graeme Ordered (22/04/22)	