

G 349432

# Fault Report

Winterton/R

Customer Name: Winterton	Date: 07/12/21
Customer Reference: 349432.	Fitter: CRAIG M
Salesperson: Dave	Salesperson called: Yes/No
Blind Type and number: Roller 349432	
Fault Description: roller measured wrong	
Action to correct: cut down roller to 1260mm (recess)	
Problem fixed on site: Yes/ <input checked="" type="radio"/> No	
Further action required: cut down roller. customer hasn't paid balance.	