

G 349646
Kung / R

Fault Report

Customer Name: Toni King

Date: 21.12.21

Customer Reference:

G 349646

Fitter:

Adam

Salesperson:

Salesperson called: Yes/No

Blind Type and number:

Vertical

Fault Description:

miss measured, Three missing vanes and two curved tracks where sent when only one was needed

Action to correct:

New Vertical 1530 by 1220
order three New Vans Drop 1470

Problem fixed on site: Yes/No

Further action required: