

G 352064
Pallett/R.

Fault Report

Customer Name: Pallett	Date: 03.02.22
Customer Reference: 352064	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: Yes/No No answer
Blind Type and number: Velux GGL7 UK04 x3 Bedroom x2 / Landing x1	
Fault Description: Side rails incorrect (too long) rail size 800mm, window sizes 740mm (tight). please note who ever returns to install needs top brackets out the unit.	
Action to correct: N/A see images attached to email	
Problem fixed on site: Yes (No)	
Further action required: needs sorted with Velux to why the incorrect size was delivered	