

G 349320

Newcastle
Council/R
(Cherry Tree)

Fault Report

Customer Name
Iumsden

Date
1/21/22

Customer Reference

Area
CRMG M

Salesperson:
Dave

Is a person named Yes/No

Blind Type and number
roller

Fault Description:

roller no 1 measured wrong
needs to be 2278 x 1085 mm
recess sizes

Action to correct:

remake roller

Problem fixed on site. Yes/No

Further action required: