

S 351348 Dunn/R1

Fault Report

Customer Name: Dunn	Date: 3/2/22
Customer Reference: 351348	Fitter: CRAIG M
Salesperson:	Salesperson called: Yes/No
Blind Type and number: CURVE TRACK	
Fault Description: need to duplicate curve track as i have bent to correct shape. (spoke to josh he said we could do it)	
Action to correct: Duplicate curve track. to book in for me to ME.	
Problem fixed on site: Yes/No	
Further action required:	