

S 351583  
Humphrey / R.

# Fault Report

Customer Name: Humphrey	Date: 14/2/22
Customer Reference: 351583	Fitter: CRAIG M
Salesperson: adam	Salesperson called: Yes/No
Blind Type and number:	
Fault Description: all p/fit measured wrong all should be 1872mm drop. customer not paid	
Action to correct: cut down or remake at 1872mm drop	
Problem fixed on site: Yes/No	
Further action required:	