


S 346002

Origlia / R.

# Fault Report

Customer Name: ORIGLIA <del>origlia</del>	Date: 17/2/22
Customer Reference: 346002	Fitter: CRAIG M
Salesperson:	Salesperson called: Yes/No
Blind Type and number: SHUTTER	
Fault Description: replace LEFT side of Right hand shutter on bay - (damaged)	
	
Action to correct: replace leg on shutter (damaged)	
Problem fixed on site: Yes/No	
Further action required: <del>Yes</del>	