

S351664
Marsden IR.

Fault Report

Customer Name: MARSDEN	Date: 17-02-22
Customer Reference: 351664	Fitter:
Salesperson:	Salesperson called: Yes/No
Blind Type and number:	
Fault Description: REQUIRES RETURN FOR (L) SIDE OF BLIND EXPRESSIONS SNOW SONA	
Action to correct: FIT RETURN ON PELMET	
Problem fixed on site: Yes/ <input checked="" type="radio"/> No	
Further action required: FIT RETURN ON PELMET & CHECK FIXINGS ON BAY	