

G 349665
Kennedy.

Fault Report

Customer Name: Kennedy	Date: 15/3/22
Customer Reference: 349665	Fitter: Craig M
Salesperson: Dave	Salesperson called: Yes/No
Blind Type and number: VERTS	
Fault Description: remove rail no ③ at 2975mm also remove rail no, NO ② BOTH at 2330mm fitting height also will need extra drops (verts) NO ③	
Action to correct: REMOVE rails also make at 2330 fitting height height	
Problem fixed on site: Yes/No	
Further action required: 2xhr only	