

G 352300
Casely IR

Fault Report

Customer Name: Casely	Date: 24.03.22
Customer Reference: 352300	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: Yes <input checked="" type="radio"/> No
Blind Type and number: Blind 1 (lounge) vertical	
Fault Description: headrail not working correctly, first runner is sticking.	
Action to correct: new headrail needs ordered	
Problem fixed on site: Yes <input checked="" type="radio"/> No	
Further action required: Order new headrail	
New h/r ordered	