

352494

## ② Fault Report

Customer Name: <i>Cummins</i>	Date: <i>09/06/22</i>
Customer Reference: <i>352494</i>	Fitter: <i>Scott Johnson</i>
Salesperson: <i>Dave</i>	Salesperson called: Yes/No <input checked="" type="radio"/>
Blind Type and number: <i>Blind 3 (KIT 2 ) Roller</i>	
Fault Description: <i>hole in fabric, See image</i>	
Action to correct: <i>N/A</i>	
Problem fixed on site: Yes/No <input checked="" type="radio"/>	
Further action required: <i>order new roller with loose controls</i>	