

G3S2526

Fault Report

Customer Name: Ward	Date: 24.05.22
Customer Reference: 352526	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: Yes <input checked="" type="radio"/> No
Blind Type and number: Blind 1 (front door) Roller	
Fault Description: Wrong fabric and chain colour.	
Action to correct: N/A	
Problem fixed on site: Yes <input checked="" type="radio"/> No	
Further action required: Order new Roller with Correct fabric and chain. Blind on hold as Dave re-visiting	