

G 352278

Cherrey. R.

# Fault Report

Customer Name: Cherrey	Date: 11/5/22
Customer Reference: 352278	Fitter: CRAIG
Salesperson: Dave	Salesperson called: Yes/No
Blind Type and number: VISION	
Fault Description: replac VISION blind fabric damaged. bk bed R window.	
Action to correct: replac blind.	
Problem fixed on site: Yes/No	
Further action required: *Blind being collected for repair * (1180x1315).	