

S350978 .

Fault Report

Customer Name: McMillan	Date: 24/9/22
Customer Reference: 350978	Fitter: CRAIG M
Salesperson:	Salesperson called: Yes/No
Blind Type and number: SHUTTERS 1+3	
Fault Description: re-order SHUTTERS NO 1+3 measured wrong	
Action to correct: NO ① SHUTTER = 543 X 1809 NO ② SHUTTER = 538 X 1809	
Problem fixed on site: Yes/No	
Further action required:	