

Fault Report

Customer Name: Dunbar	Date: 22/6/22
Customer Reference: 352615	Fitter: CRAIG M
Salesperson:	Salesperson called: Yes/No
Blind Type and number: pleated	
Fault Description: replace pleated blind fr left bed has holes in fabric	
Action to correct: replace pleated	
Problem fixed on site: Yes/No	
Further action required:	