

S351207

Fault Report

Customer Name: <u>Rooke</u>	Date: <u>2/12/22</u>
Customer Reference: <u>351207</u>	Fitter: <u>WATNE</u>
Salesperson:	Salesperson called: Yes/No <u>(No)</u>
Blind Type and number: <u>Rotan</u>	
Fault Description: <p style="text-align: center;">BLIND NOT FITTED TO CUSTOMERS SPECIFICATION</p>	
Action to correct: <p style="text-align: center;">CUSTOMER WANTED BLIND TO PASS WINDOW SILL, WHEN BLIND MOVED HOLES WERE VISIBAL, CUSTOMER REQUIRES NEW BLIND, 45mm TO BE ADDED ONTO DROP</p>	
Problem fixed on site: Yes/No	
Further action required:	