

352526

② Fault Report

Customer Name: Ward	Date: 27/7/22
Customer Reference: 352526	Fitter: CRAIG M
Salesperson:	Salesperson called: Yes/No
Blind Type and number: roller	
Fault Description: need to take out chain and end caps for roller. should be bronze. (on front door)	
Action to correct: Take out bronze chain and end caps for roller on front door.	
Problem fixed on site: Yes/No	
Further action required:	