

# Fault Report

Customer Name: <a href="#">Dorman</a>	Date: <a href="#">04.08.22</a>
Customer Reference: <a href="#">3488454</a>	Fitter: <a href="#">Scott Johnson</a>
Salesperson: <a href="#">Dave</a>	Salesperson called: <a href="#">No</a>
Blind Type and number: <a href="#">Roller</a>	
Fault Description: <a href="#">Customer has had windows replaced and there is an additional trim 5mm needs took of both blinds</a>	
Action to correct: <a href="#">N/A</a>	
Problem fixed on site: <a href="#">No</a>	
Further action required: <a href="#">cut Blinds and sent back for installation.</a>	