

# Fault Report

Customer Name: <i>Webb</i>	Date: <del>352</del> <i>23/8/22</i>
Customer Reference: <i>352905</i>	Fitter: <i>CNA G M</i>
Salesperson:	Salesperson called: Yes/No
Blind Type and number: <i>Roman</i>	
Fault Description: <i>re-order Roman in utility measured wing on drop needs to be 990mm on drop</i>	
Action to correct: <i>re-order roman (utility) 990mm on dep</i>	
Problem fixed on site: Yes/No	
Further action required:	