

G352897

Fault Report

Customer Name: <i>Lively</i>	Date: <i>8/9/22</i>
Customer Reference: <i>352897</i>	Fitter: <i>CRAIG M</i>
Salesperson:	Salesperson called: Yes/No
Blind Type and number: <i>pleat</i>	
Fault Description: <i>CUT down pleat no 4 TO 670 mm as catching cons roof bar</i>	
Action to correct: <i>CUT down pleat no 4 TO 670 mm</i>	
Problem fixed on site: Yes/No	
Further action required:	