

# Fault Report

Customer Name: <i>Willis</i>	Date: <i>4-10-99</i>
Customer Reference: <i>352996</i>	Fitter: <i>Wylie</i>
Salesperson:	Salesperson called: Yes/No <input checked="" type="radio"/>

Blind Type and number: *Pac*

Fault Description: *CUSTOMER REQUESTED A SHORTER  
Pole, Replaced Pac is still  
A LONG ONE*

Action to correct:  
*SHORTER Pole Required  
MAYBE INETER LENGTH*

Problem fixed on site: Yes/No

Further action required: