

C352816.

# ③ Fault Report

Customer Name: Brightley	Date: 18.10.22
Customer Reference: 352816	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: Pleated blind	
Fault Description: Please see attached image, customer need this part for the pleated blind.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Order new part to be delivered to the customers address, they will install it themselves.	