


G353108.

# Fault Report

Customer Name: <i>Smith</i>	Date: <i>21/10/22</i>
Customer Reference: <i>353108</i>	Fitter: <i>Craig M</i>
Salesperson:	Salesperson called: Yes/No
Blind Type and number: <i>PIfit</i>	
Fault Description: <i>(replace bottom frame on pifit (scratched))</i>	
Action to correct: 	
Problem fixed on site: Yes/No	
Further action required:	