

G353283.

Fault Report

Customer Name: JONES	Date: 27-10-22
Customer Reference: 353283	Fitter: WATNC
Salesperson: DAVE	Salesperson called: Yes (No)
Blind Type and number: ROLLER BLIND 9	
Fault Description: SMALL HOLE IN BLIND	
Action to correct: NEW BLIND REQUIRED	
Problem fixed on site: Yes (No)	
Further action required:	