

G, 353467 / R.

Fault Report

Customer Name: Clark	Date: 14.12.22
Customer Reference: 353467	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: Roller, Roller 3 & 4 (Mid bedroom & RH front bed 1)	
Fault Description: Holes in fabric, photo sent to Nicole.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Order new blinds.	