

G353471

TATTERDALL

# Fault Report

Customer Name: TATTERDALL	Date: 03/05/23
Customer Reference: 353471	Fitter: CRAGG M
Salesperson:	Salesperson called: Yes/No
Blind Type and number: SHUTTER	
Fault Description: SHUTTER measured wrong and also should have been PVC NOT WOOD	
Action to correct: customer not sure what to do either to get deposit back or wait to re-order.	
Problem fixed on site: Yes/No	
Further action required:	