

C1353384

# Fault Report

Customer Name: KARNOS	Date: 31/11/22
Customer Reference: 353384	Filter: WATNE
Salesperson:	Salesperson called: Yes/No
Blind Type and number: VERTICAL CURVED Blind 1	
Fault Description: NO VEINS	
Action to correct: VEINS REQUIRED	
Problem fixed on site: Yes/No	
Further action required:	