

5350965

Fault Report

Customer Name: 350965	Date: 30/11/22
Customer Reference: Leak - bencham	Fitter: CRAIG M
Salesperson:	Salesperson called: Yes/No
Blind Type and number: SHUTTER CATCH PLATES	
Fault Description: Need 8 x frame catch plates as missing from 2 shutters	
Action to correct: Send catch plates for 2x shutters x <u>8</u>	
Problem fixed on site: Yes/No	
Further action required:	