

G352937

# Fault Report

Customer Name: <i>Strayhorn</i>	Date: <i>6/12/22</i>
Customer Reference: <i>352937</i>	Fitter: <i>CRAIG M</i>
Salesperson:	Salesperson called: Yes/No
Blind Type and number: <i>SHUTTER catch plates</i>	
Fault Description: <i>Need 8 x shutter frame catch plates (missing)</i>	
Action to correct: <i>Take out 8 x frame catch plates (missing)</i>	
Problem fixed on site: Yes/No	
Further action required:	