

Fault Report

Customer Name: <i>lee</i>	Date: <i>19/12/22</i>
Customer Reference: <i>353535</i>	Fitter: <i>CRISTIN</i>
Salesperson: <i>Dave</i>	Salesperson called: Yes/No
Blind Type and number:	
Fault Description: <i>remake vanes NO ② at 1165mm also headrail NO ① at 1950mm measured wrong</i>	
Action to correct: <i>remake headrail NO ① 1950mm Vanes NO ② 1165mm</i>	
Problem fixed on site: Yes/No	
Further action required:	