

S 354203

Fault Report

Customer Name: Kirkup	Date: 08.12.22
Customer Reference: 354203	Fitter: Scott Johnson
Salesperson: Shaun Hanley	Salesperson called: No
Blind Type and number: Velux, Bathroom	
Fault Description: Not sure how but the strings are too long and can't be adjusted maybe a manufacturing fault.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Order new Blind.	