

S 354339  
Todd/R

# Fault Report

Customer Name: Todd	Date: 21/12/22
Customer Reference: 354339	Fitter: CRANE M
Salesperson:	Salesperson called: Yes/No
Blind Type and number: roller no 6	
Fault Description: replace roller no 6 as fabric marked.	
Action to correct: replace roller no 6 1320 x 2000	
Problem fixed on site: Yes/No	
Further action required:	