

G 353433

BARNES

# Fault Report

Customer Name: Barnes	Date: 09.01.23
Customer Reference: 353433	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: Wood Venetian, Porch	
Fault Description: Pelmet needs to be left hand return, 800mm pelmet with a LH return is needed.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Order pelmet and return.	