

S354442

WATKIN

Fault Report

Customer Name: Watkin	Date: 07.02.23
Customer Reference: 354442	Fitter: Scott Johnson
Salesperson: Shaun Hanley	Salesperson called: No
Blind Type and number: Vertical (Slats only)	
Fault Description: One set of slats sent the incorrect size should be as measured slates set 6 14nr x 2146mm.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Order new set of vanes.	