

G 353663

Fault Report

Customer Name: HOGG	Date: 23/02/23
Customer Reference: 353663	Fitter: CRAIG
Salesperson: DAVE	Salesperson called: Yes/No
Blind Type and number: WOOD VENETIANS	
Fault Description: ALL BLINDS HAVE BEEN MADE 25MM SLAT WIDTH AND SHOULD HAVE BEEN 50MM	
Action to correct: REORDED ALL BLINDS IN 50MM SLAT WIDTH AS REQUESTED ON TICKET 353663	
Problem fixed on site: Yes/No	
Further action required:	