

S354102
WALTON.

③ Fault Report

Customer Name: Walton	Date: 14.03.23
Customer Reference: 354102	Fitter: Scott Johnson
Salesperson: Shaun Hanley	Salesperson called: No
Blind Type and number: Roller, bedroom patio R and living room patio L & R	
Fault Description: These 3 rollers need reduced in size (width). Bedroom Patio R -10mm, Living room patio L -10mm, Living room patio R -5mm.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Cut down blinds that are in the unit.	