

G 353764

WARD

Fault Report

Customer Name: ward	Date:
Customer Reference: 353764	Fitter: CRAMA M
Salesperson:	Salesperson called: Yes/No
Blind Type and number: roller components	
Fault Description: components missing: need. ✓ x chrome end caps ✓ x chrome chain, ✓ x white chain and 3/✓ x white end caps	
Action to correct:	
Problem fixed on site: Yes/No	
Further action required:	