

S354531  
LOWES

# Fault Report

Customer Name: Lowes	Date: 29.03.23
Customer Reference: 354531	Fitter: Scott Johnson
Salesperson: Shaun Hanley	Salesperson called: Yes
Blind Type and number: Rollers in cassettes, Study Bay 1&3	
Fault Description: Rollers measured incorrectly, Bay 1 445mm and bay 3 440mm, sizes are measured tight from wall to the cassette on bay 3, please speak to Graeme to achieve the correct sizes needed.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: After discussing with Graeme remake the rollers.	