

G353764

WARD

## ② Fault Report

Customer Name: Ward	Date: 12.04.23
Customer Reference: 353764	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: Roller, Kitchen door	
Fault Description: There is a crease in the fabric which was left to see if it would fall out, but the crease is still there. Roller should have chrome chains and end caps on the bottom bar.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Order new roller.	