

S 354744

VASARHELYI

Fault Report

Customer Name: Vasarhelyi	Date: 13/4/23
Customer Reference: 354744	Fitter: CRACKI M
Salesperson:	Salesperson called: Yes/No
Blind Type and number: WOOD VEN	
Fault Description: replace wood ven as it should have HAD TAPES	
Action to correct: re-order blind with tapes	
Problem fixed on site: Yes/No	
Further action required:	