

G353144
RYAN1

② Fault Report

Customer Name: Ryan	Date: 20/04/23
Customer Reference: 353144	Fitter: CRAIG M
Salesperson:	Salesperson called: Yes/No
Blind Type and number: SHUTTERS	
Fault Description: Need to take 2x cover strips (battens) at 15x60x1750mm	
Action to correct: Take out cover strips	
Problem fixed on site: Yes/No	
Further action required:	