

Fault Report

Customer Name: HARTLEY Date: 10/05/23

Customer Reference: 354681 Fitter:

Salesperson: SHARON Salesperson booked: Yes/No

Blind Type and number: IX PERFECT FIT ROLLER

Fault Description: FABRIC TORN

Action to correct: REPLACE FABRIC ON ROLLER TO UNILUX WHITE

Problem fixed on site: Yes/No No

Further action required:

* PLEASE PICK UP FROM SPENNYMOOR SHOP