

S354913

COLBURN

Fault Report

Customer Name: colburn	Date: 28/6/23
Customer Reference: 354913	Fitter: CRAIG IN
Salesperson:	Salesperson called: Yes/No
Blind Type and number: roller (kit)	
Fault Description: remove roller no ① kitchen. must be in a cassette.	
Action to correct: remove kit roller in cassette. £169.50 paid £81.50 to pay	
Problem fixed on site: Yes/No	
Further action required:	