

G353913

FERRI

Fault Report

Customer Name: <i>ferri</i>	Date:
Customer Reference: <i>353913</i>	Fitter:
Salesperson:	Salesperson called: Yes/No
Blind Type and number: <i>rollers nos 2,3,4</i>	
Fault Description: rollers <i>CUT down rollers</i> <i>NO2 2775 width</i> <i>NO3 2740 width</i> <i>NO4 2745 width</i>	
Action to correct: <i>CUT down rollers (measured wrong)</i> <i>NO2 = 2775 mm</i> <i>NO3 = 2740 mm</i> <i>NO4 = 2745 mm</i>	
Problem fixed on site: Yes/No	
Further action required:	