

S354678

TURNER

Fault Report

Customer Name: <i>Turner</i>	Date:
Customer Reference: <i>354678</i>	Fitter: <i>CRAIG M</i>
Salesperson:	Salesperson called: Yes/No
Blind Type and number: <i>Verticals</i>	
Fault Description: <i>replace rails no's 1+4 made wrong also need extra vanes for both</i>	
Action to correct: <i>replace rails nos 1+4 (made wrong) also extra vanes needed</i> <i>NOT PAID</i>	
Problem fixed on site: Yes/No	
Further action required:	

*sub
rader*